

FIG. 1




FIG. 2A




FIG. 2B




FIG. 2C




FIG. 2D




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9A




FIG. 9B




FIG. 10




FIG. 11A

11008
↓




FIG. 11B




FIG. 12





Fig. 13A






FIG. 14




FIG. 15




FIG. 16




FIG. 17A




FIG. 17B




FIG. 18A




FIG. 18B




FIG. 19

1715




FIG. 20A




FIG. 20B




FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25




FIG. 24





FIG. 27



Biquad section

Notch section

Fig. 28A




Fig 28B



FIG. 29A



FIG. 29B



FIG. 29C




Fig. 29D




Fig. 29E




Fig. 29F




FIG. 30A




FIG. 30B




Fig. 30c

FIG. 31




FIG. 32




FIG. 33




FIG. 34





FIG. 35






FIG. 36A




FIG. 36B




FIG. 37A




FIG. 37B




FIG. 38




FIG. 39




FIG. 40